From:
 Coltrain, Katrina

 To:
 Meyer, John

 Cc:
 R6HarveyInfo

Subject: RE: M6H1-Harvey Response--Rapid Response Assessment and Inspection Sheet

Date: Saturday, September 2, 2017 10:51:24 AM

Attachments: Hurricane Harvey rapid response and inspection sheet t 9-2-17 updated.xlsx

I apologize for this---US Oil has a complete date entered. It should be blank.

Katrina Higgins-Coltrain Remedial Project Manager US EPA Region 6 LA/OK/NM Section (6SF-RL) 1445 Ross Avenue Dallas, Texas 75202 214-665-8143

From: Meyer, John

Sent: Saturday, September 02, 2017 10:34 AM **To:** Coltrain, Katrina <coltrain.katrina@epa.gov> **Cc:** R6HarveyInfo <R6HarveyInfo@epa.gov>

Subject: RE: M6H1-Harvey Response--Rapid Response Assessment and Inspection Sheet

I made a few minor edits and sent on. Thanks for your quick action.

John C Meyer Remedial Branch Chief Superfund Division 214.665.6742



From: Coltrain, Katrina

Sent: Saturday, September 02, 2017 9:06 AM **To:** Meyer, John < Meyer.John@epa.gov > **Cc:** R6HarveyInfo < R6HarveyInfo@epa.gov >

Subject: RE: M6H1-Harvey Response--Rapid Response Assessment and Inspection Sheet

Updated Table: completed column populated and status summary updated at bottom of table.

Katrina Higgins-Coltrain Remedial Project Manager US EPA Region 6 LA/OK/NM Section (6SF-RL) 1445 Ross Avenue Dallas, Texas 75202 214-665-8143

From: Coltrain, Katrina

Sent: Friday, September 01, 2017 6:38 PM **To:** Meyer, John < Meyer. John@epa.gov > **Cc:** R6HarveyInfo@epa.gov >

Subject: M6H1-Harvey Response--Rapid Response Assessment and Inspection Sheet

Please find attached the Rapid Response Assessment and Inspection Sheet.

Katrina Higgins-Coltrain Remedial Project Manager US EPA Region 6 LA/OK/NM Section (6SF-RL) 1445 Ross Avenue Dallas, Texas 75202 214-665-8143